


WIRING DIAGRAMME

CLASS 4/4+ with PTC start



1. COMPRESSOR
2. THERMOSTAT
3. CONDENSER FAN MOTOR
4. ALARM CONTROL LAMP RED
5. SWITCH FOR QUICK FREEZE
6. QUICK FREEZE LAMP YELLOW
7. MAINS CONTROL LAMP GREEN
8. BALL SWITCH
9. INTERNAL LID LIGHT